

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No 128179

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080199-4

RECEIVED FROM

DATE REC'D 1-2-57

P. O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W. O. NO.
322	000000	00000	00000	0	0	00	00	0	0
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	REMARKS	
							ACCEPTED	REJECTED	
2	738246 BRKT ASSY'S SWITCH ALN3-1						2		
	SHIP MEMO 35866								
<p>RECEIVED BY <i>[Signature]</i> INSPECTED BY <i>[Signature]</i> DATE 1/22/57</p> <p>REJECTS RETURNED ON SHIP MEMO NO.</p>									

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF.

No 128180

RECEIVED FROM

DATE REC'D 1-2-57

P. O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W. O. NO.
322	000000	00000	00000	0	0	00	00	0	0
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	REMARKS	
							ACCEPTED	REJECTED	
10	732345 BEARING CAM BRACKET						10		
	SHIP MEMO 35869								
<p>RECEIVED BY <i>[Signature]</i> INSPECTED BY <i>[Signature]</i> DATE 1/22/57</p> <p>REJECTS RETURNED ON SHIP MEMO NO.</p>									

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080199-4